



Department of
Environmental
Conservation

Tonawanda Community Working Group

Superfund and Brownfield Progress Update

May 26, 2021



Author: Ben McPherson Revised: 10/9/2020 N:\private\RR\Tonawanda Coke\Figure 1 - Site Location Map.mxd

Brownfield Site

Riverview Innovation &
Technology Campus,
#C915353

Work Plan/Report	Submitted	Status	Progress
Interim Site Management Plan (ISMP)	3/6/2020	DEC Approved	Continuous
Light Oil Area Secondary Containment Investigation Work Plan	3/6/2020	DEC Approved	Complete
Remedial Investigation Work Plan	3/12/2020	DEC Approved	Complete (field)
Stormwater Pollution Prevention Plan	3/12/2020	DEC Approved	Continuous
Storm Sewer IRM Work Plan	4/12/2020	DEC Approved	Complete
Mixing Pad IRM Work Plan	5/5/2020	DEC Approved	Ongoing
PCC Excavation Work Plan	5/11/2020	DEC Approved	Complete
ISMP - Work Scope 2	5/11/2020	DEC Approved	Ongoing
Container Management IRM Work Plan	6/17/2020	DEC Approved	Pending Final Disposal
ISMP - Work Scope 3	7/6/2020	DEC Approved	Ongoing
Storm Sewer IRM Phase 1 Report	8/5/2020	DEC Approved	Complete
Abandoned Pipeline IRM Work Plan	8/19/2020	DEC Approved	Complete
PCC Grading Concept Plan	9/10/2020	DEC Approved	Complete
South Road Reconstruction Plan	11/17/2020	DEC Approved	Complete
Surface Water Phase 3 Work Plan	12/22/2020	DEC Approved	Complete

Work Plan/Report	Submitted	Status	Progress
AST Management Work Plan	12/23/2020	DEC Approved	Ongoing
Abandoned Pipeline IRM Report	1/20/2021	DEC to Review	N/A
Building Demolition Work Plan	1/26/2021	DEC Approved	Ongoing
PBS/CBS Tank Work Plan	2/15/2021	DEC Approved	Pending
Access to Coal Breaker Building	2/15/2021	DEC Approved	Complete
Secondary Containment Investigation Work Plan	3/10/2021	DEC Approved	Ongoing
Box Culvert Lining Work Plan	4/2/2021	DEC Approved	Ongoing



AST Tank Summary

- Multiple work plans for the aboveground storage tanks (ASTs):
 - A. *Aboveground Storage Tank Management Interim Remedial Measures Work Plan*;
 - B. *CBS and PBS Tank Closure Work Plan*; and
 - C. *Secondary Containment IRM Work Plan – Closure*.
- Plans A and B govern the characterization, disconnection, cleaning, and removal of tanks and tank contents.
- Plan C governs investigating secondary containment areas surrounding tanks to determine if any releases have occurred, and to assess to what extent.



Photo: <http://www.riverviewtechcampus.com/photos/#gallery-brownfield-35>



Photo: <http://www.riverviewtechcampus.com/photos/#gallery-brownfield-38>

Superfund Site

Tonawanda Coke, #915055

Investigation Status

Site 108:

- Access agreement is in place for remaining work
- Wetlands permit from USACE needed after access agreement.
- Working on schedule to complete remaining scope.

Site 109:

- All field work completed.
- A second round of groundwater sampling is to coincide with Site 108/110 work.

Site 110:

- Access agreement is in place for remaining work.
- Working on schedule to complete remaining scope and additional work to fill data gaps.

Thank You

NYSDEC Project Manager:

Benjamin McPherson
270 Michigan Avenue
Buffalo, NY 14203
(716) 851-7220
benjamin.mcpherson@dec.ny.gov

NYSDOH Project Manager:

Angela Martin
Bureau of Environmental
Exposure Investigation
Corning Tower, Room 1787
Albany, NY 12237
(518) 473-4671
bee@health.ny.gov

USEPA:

Michael Basile
Basile.Michael@epa.gov